ALL RENTAL RETURN TOOLS FROM EXTERNAL / INTERNAL SHOULD CARRIED WITH FOLLOWING INSPECTION & MAINTENANCE ROUTING, MFG OEM STD AS WELL AS COMPLETE GLOBAL MINIMUM DOCUMENTATION

INSPECTION & MAINTENANCE ROUTING INSTRUCTION FOR MK3 CLEARMAX CASING SCRAPER 6.63-10.75" CSG :-

01. VISUAL INSPECTION
02. DISMANTLE ALL THE SPARE PARTS (QUALITY INSPETION)
03. WASHING AND BUFFING RE-USEABLE SPARE PARTS
04. INSPECTION (FIELD INSPECTION)
05. RE-DRESSING THE TOOL (QUALITY INSPETION - FILL FQF)
06. PAINTING
07. STORAGE PREPARATION

MINIMUM DOCUMENTS REQUIREMENT FOR R&M:-

01 MAINTENANCE, INSPECTION & REPAIR (MIR)
02 FIELD QUALITY FORM (FQF)
03 FULL MPI INSPECTION REPORT